

Manual Revision and Date	Change
F	<ul style="list-style-type: none"> Manual revised to support the following relay changes: <ul style="list-style-type: none"> Six additional control output options. Two additional reclose time delay options. Y-type power supply option. Reset timer 1-100 second time delay option. Four additional special contact assignments options. A four function field selectable logic switch. Moved sensing input power module from outside the case to inside the case. Added Section 7, <i>Difference Data</i>, to support BE1-79M Relay revision D and previous.
E	<ul style="list-style-type: none"> Operational test procedure revised. Pages 5-5 and 5-6 added. Section 6 added.
D	<ul style="list-style-type: none"> Page 3-9: Subsection entitled <u>Reclosing Event Memory</u> rewritten for clarification. Pages 4-2 through 4-5: Operational test procedure revised. Pages 5-2 through 5-4: Subsection entitled <u>Test Plug Adapter</u> added. Added Qualifications to specifications listing, revised isolation test and dielectric test.
C	<ul style="list-style-type: none"> Page 3-2: Added footnote to Table 3-1. Added two paragraphs beginning with “Each reclose attempt...” Page 3-7 Figure 3-2 corrected.
B	<ul style="list-style-type: none"> Page 3-3: Subsection entitled <i>Instantaneous Trip Enable</i> clarified.
A	<ul style="list-style-type: none"> Manual revised to reflect software changes, which introduced an additional category (Unsuccessful Reclosers) to the Reclose Event Memory.
—, 01/86	<ul style="list-style-type: none"> Initial release