


DFG-M (400 V AC / 3~)

Technical specifications from the motor label:

1	BAVE + KDPV
2	1000
3	1000
4	1000
5	1000
6	1000
7	1000
8	1000
9	1000
10	1000
11	1000
12	1000
13	1000
14	1000
15	1000
16	1000
17	1000
18	1000
19	1000
20	1000
21	1000
22	1000
23	1000
24	1000
25	1000
26	1000
27	1000
28	1000
29	1000
30	1000
31	1000
32	1000
33	1000
34	1000
35	1000
36	1000
37	1000
38	1000
39	1000
40	1000
41	1000
42	1000
43	1000
44	1000
45	1000
46	1000
47	1000
48	1000
49	1000
50	1000
51	1000
52	1000
53	1000
54	1000
55	1000
56	1000
57	1000
58	1000
59	1000
60	1000
61	1000
62	1000
63	1000
64	1000
65	1000
66	1000
67	1000
68	1000
69	1000
70	1000
71	1000
72	1000
73	1000
74	1000
75	1000
76	1000
77	1000
78	1000
79	1000
80	1000
81	1000
82	1000
83	1000
84	1000
85	1000
86	1000
87	1000
88	1000
89	1000
90	1000
91	1000
92	1000
93	1000
94	1000
95	1000
96	1000
97	1000
98	1000
99	1000
100	1000

06-1-40-11 state: 09.14EN




With the reduction in pairs (7 - 12 pressure connections) **the reductions from the order key double**, as each pressure connection only gets a pressure pulse with every second turning of the pump shaft or the stroke washer.

The arrangement of the pressure connections and the suction connection is done in the order of the numbering. If another arrangement should be desired, please indicate it when the order is placed.

Spare part number:

Pos. 1 Three phase a.c. motor:	00000102000037
Pos. 2 Bottom flange:	F0036/01-10
Pos. 3 Coupling:	FWZ00449-02
Pos. 4 Retaining ring:	0802100006
Pos. 5 Drive shaft:	acc. to 66/005.1
Pos. 6 Cross key:	F0066/05-02
Pos. 7 Hexagon bolt M8x20:	09i0401701111
Pos. 8 Toothed washer A 8,4:	0906797007111
Pos. 9 Hexagon bolt M6x20:	09i0401700411
Pos.10 Toothed washer A 6,4:	0906797003111

Sectional drawing for spare part no.:



Subject to alterations!

© BEKA 2014 All rights reserved!